

Job name: Inspect Weir Flow Plate, Screen Mesh & Replace Floor 1.5

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 106 m2

Picture



Before



After

Remark:

Date: 6/8/2023