

Report

Remove and Installation Insulation Lagging BFS Boiler

Unit.2 Floor.7

Location

Boiler Unit.2 floor.7

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

1-3 Feb 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

0002RP 02/25

Scope of Work

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation New Insulation
5. Installation Lagging
6. Finish

Work Procedure

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation New Insulation
5. Installation Lagging
6. Finish





One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	<i>Remove and Installation Insulation Lagging</i>	Equipment Item	<i>Boiler Unit.2 floor.7</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Remove and Installation Insulation Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>1-3 Feb 2025</i>



<i>Description: Remove and Installation Insulation Lagging</i>
--