

Report

***Remove and Modify Insulation Lagging Wall Tube Boiler
Unit.2 Floor3, Floor.6***

Location

Boiler Unit.2Floor.3,Floor.6

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

13-20 May 2025

<i>ContractorInspection</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Approved</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>
---	---	--	--

0100 RP100/25

Scope of Work

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation Insulation**
- 5.Modify Lagging**
- 6.Finish**

Work Procedure

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4. Re-Installation Insulation**
- 5.Modify Lagging**
- 6.Finish**




One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	<i>Remove and Modify Insulation Lagging</i>	<i>Equipment Item</i>	<i>Boiler Unit.2Floor.3,Foor.6</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Remove and Modify Insulation Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>13-20 May 2025</i>



Description: Remove and Modify Insulation Lagging

