

Daily Report

Job name: Expansion Joint Booster Fan A

Description: Installation Insulation and Lagging 100%

Picture



Remark:

Date: 16/01/2024

Daily Report

Job name: Expansion Joint Booster Fan B

Description: Installation Insulation and Lagging 100%

Picture



Remark:


Date: 16/01/2024

Daily Report

Job name: Expansion Joint ID Fan B

Description: Installation Insulation and Lagging 100%

Picture



Remark:


Date: 16/01/2024

Daily Report

Job name: Expansion Joint Outlet FGD

Description: Installation Insulation and Lagging 100%

Picture



Remark:


Date: 16/01/2024

Daily Report

Job name: Expansion Joint Absorber Outlet to Clean Gas

Description: Installation Expansion Joint Frame 60%

Picture



Remark:

Date: 16/01/2024

Daily Report

Job name: Expansion Joint Inlet ESP No.2

Description: Repair Liner 80%

Picture



Remark:

Date: 16/01/2024

Daily Report

Job name: Expansion Joint Inlet ESP No.6

Description: Repair Liner 80%

Picture



Remark:


Date: 16/01/2024

Daily Report

Job name: Expansion Joint Outlet BUF

Description: Installation Liner 100%

Picture



Remark:

Date: 16/01/2024

Daily Report

Job name: Expansion Joint Outlet Clean Gas

Description: Installation Liner 80%

Picture



Remark:

Date: 16/01/2024