

Daily Report

Job name: Expansion Joint Inlet ESP No.2

Description: Installation Insulation Lagging 100%

Picture



Remark:



Date: 22/01/2024

Daily Report

Job name: Expansion Joint Inlet ESP No.6

Description: Installation Insulation Lagging 100%

Picture



Remark:



Date: 22/01/2024

Daily Report

Job name: Expansion Joint Absorber Outlet to Clean Gas

Description: Installation Expansion Joint Frame 90%

Picture



Remark:

Date: 22/01/2024

Daily Report

Job name: Expansion Joint Outlet BUF

Description: Installation Line Drain 80%

Picture



Remark:

Date: 22/01/2024

Daily Report

Job name: Expansion Joint Outlet FGD

Description: Installation Line Drain 80%

Picture



Remark:

Date: 22/01/2024