


Job name: HP Heater 2 Floor 3

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 1 m2

Picture



Before



After

Remark:

Date: 2/8/2023