

Job name: HP Heater 6 Floor 3

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 2 m2

Picture



Before



After

Remark:

Date: 2/8/2023