

Job name: ฝา Manhole LP Heater No.5 Floor 2

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 3 m2

Picture



Before



After

Remark:

Date: 7/8/2023