

Report

***Repair and Replacement Insulation Lagging Wall
Economizer Outlet Duct to APH Boiler Unit.3 Floor.4***

***Location
Boiler Unit.3 floor.4***

***Owner
Hongsa Power***

***By
One Volts Service Co.,Ltd.***

***Work Duration
15 Feb 2025***

<i>Contractor Inspection</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Approved</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>
--	---	--	--

Scope of Work

1. Inspection
2. Repair Lagging
3. Installation New Lagging
4. Finish

Work Procedure

1. Inspection
2. Repair Lagging
3. Installation New Lagging
4. Finish





One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	Repair and Replacement Insulation Lagging	Equipment Item	Boiler Unit.3 floor.4
Contractor	One Volts Service Co.,Ltd.	Job Description:	Repair and Replacement Insulation Lagging
Customer:	Hongsa Power Co.,Ltd	Start - Ending	15 Feb 2025



Description: Repair and Replacement Insulation Lagging