

Report

***Remove and Replacement Insulation Lagging Reheater
Desuperheating A,B Boiler Unit3 Floor7***

***Location
Boiler Unit.3 floor.7***

***Owner
Hongsa Power***

***By
One Volts Service Co.,Ltd.***

***Work Duration
15 Feb 2025***

<i>ContractorInspection</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Approved</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>
---	---	--	--

Scope of Work

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Installation New Insulation**
- 5.Installation New Lagging**
- 6.Finish**

Work Procedure

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Installation New Insulation**
- 5.Installation New Lagging**
- 6.Finish**



One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	Remove and Replacement Insulation Lagging	Equipment Item	Boiler Unit.3 floor.4
Contractor	One Volts Service Co.,Ltd.	Job Description:	Remove and Replacement Insulation Lagging
Customer:	Hongsa Power Co.,Ltd	Start - Ending	15 Feb 2025



Description: Remove and Replacement Insulation Lagging

