

Report

***Remove and Re-installation Insulation Lagging Boiler Line
Drain Soot Boiler Unit.1 floor.2***

Location

Boiler Unit.1 floor.2

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

20 Feb 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

0053 RP 57/25

Scope of Work

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation Lagging
3. Finish

Work Procedure

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation Lagging
3. Finish



One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	Remove and Re-Installation Insulation	Equipment Item	Boiler Unit.1 floor.2
Contractor	One Volts Service Co.,Ltd.	Job Description:	Remove and Re-Installation Insulation
Customer:	Hongsa Power Co.,Ltd	Start - Ending	20 Feb 2025



Description: Remove and Re-Installation Insulation