

Report

Modify Lagging Line LP Cylinder gland Steam Turbine

Location

Steam Turbine floor.2 Unit.3

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

22 Feb 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

Scope of Work

1. Repair Lagging
2. Installation new Lagging
3. Finish

Work Procedure

1. Repair Lagging
2. Installation new Lagging
3. Finish



One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	<i>Modify Lagging</i>	Equipment Item	<i>Line LP Cylinder gland Steam Turbine</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Modify Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>22 Feb 2025</i>



Description :

Modify Lagging

