

Report

Remove and Re-installation Insulation Lagging Valve Turbine

Location

Steam Turbine Unit.3 Floor.2.5

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

24 Feb 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

Scope of Work

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation new Insulation
5. Install Lagging

Work Procedure

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation new Insulation
5. Install Lagging



One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	<i>Remove and Re-Installation Insulation Lagging</i>	Equipment Item	<i>Steam Turbine Unit.3 floor.2.5</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Remove and Re-Installation Insulation Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>24 Feb 2025</i>



Description: Remove and Re-Installation Insulation Lagging