

Report

Remove and Reinstallation Insulation Lagging Fan Mill 37

Boiler Unit 3 Floor 2

Location

Boiler Unit.3 floor.2

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

30-02 Jan 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

1317RP 17/24

Scope of Work

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation Insulation
5. Installation Lagging
6. Finish

Work Procedure

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation Insulation
5. Installation Lagging
6. Finish



One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	Remove and Reinstallation Insulation Lagging	Equipment Item	Boiler Unit.3 floor.2
Contractor	One Volts Service Co.,Ltd.	Job Description:	Remove and Reinstallation Insulation Lagging
Customer:	Hongsa Power Co.,Ltd	Start - Ending	30-02 Jan 2025



Description: Remove and Re-Installation Insulation Lagging