

Report

***Remove and Re-Installtion Insulation Lagging wall EPS 111A
Unit.2***

***Location
EPS 111A Unit.2***

***Owner
Hongsa Power***

***By
One Volts Service Co.,Ltd.***

***Work Duration
18-20 Apr 2025***

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

0090 RP 90/25

Scope of Work

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation New Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**

Work Procedure

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation New Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**



One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

<i>Project :</i>	<i>Remove and Re-installation Insulation Lagging</i>	<i>Equipment Item</i>	<i>EPS 111A Unit.2</i>
<i>Contractor</i>	<i>One Volts Service Co.,Ltd.</i>	<i>Job Description:</i>	<i>Remove and Re-installation Insulation Lagging</i>
<i>Customer:</i>	<i>Hongsa Power Co.,Ltd</i>	<i>Start - Ending</i>	<i>18-20 Apr 2025</i>



Description: Remove and Re-installation Insulation Lagging

