

Report

***Remove and Replacement Insulation Lagging Water Wall
Lower Header Boiler Unit.3 floor.1.5***

Location

Boiler Unit.3 floor.1.5

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

12-25 Feb 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

0043RP 43/25

Scope of Work

1. Inspection
2. Remove Lagging
3. Installation New Lagging
4. Finish

Work Procedure

1. Inspection
2. Remove Lagging
3. Installation New Lagging
4. Finish




One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	Remove and Replacement Insulation Lagging	Equipment Item	Boiler Unit.3 floor.1.5
Contractor	One Volts Service Co.,Ltd.	Job Description:	Remove and Replacement Insulation Lagging
Customer:	Hongsa Power Co.,Ltd	Start - Ending	12-25 Feb 2025



Description: Remove and Replacement Insulation Lagging