

Report

***Remove and Replacement Insulation Lagging Line Drain Soot
Boiler Unit.3 Floor.2***

***Location
Boiler Unit.3 Floor.2***

***Owner
Hongsa Power***

***By
One Volts Service Co.,Ltd.***

***Work Duration
28-31 May 2025***

<i>ContractorInspection</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Approved</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>
---	---	--	--

0108 RP108/25

Scope of Work

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Replacement Insulation
5. Replacement Lagging
6. Finish

Work Procedure

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Replacement Insulation
5. Replacement Lagging
6. Finish



One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	<i>Remove and Replacement Insulation Lagging</i>	<i>Equipment Item</i>	<i>Boiler Unit.3 Floor.2</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Remove and Replacement Insulation Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>28-31 May 2025</i>



Description: Remove and Replacement Insulation Lagging

