

Report

***Remove and Re-Installation Insulation Lagging Inner Aux
Electeick Valve No.2 Steam Turbine Unit.1 Floor3***

Location

Turbine Unit.1 Floor3

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

1-20 July 2025

<i>ContractorInspection</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Approved</i> (.....) <i>One Volts Service Co.,Ltd</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>	<i>Commission Inspector</i> (.....) <i>Hongsa Power</i>
---	---	--	--

0156 RP156/25

Scope of Work

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation New Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**

Work Procedure

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation New Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**



One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

<i>Project :</i>	<i>Remove and Re-Installation Insulation Lagging</i>	<i>Equipment Item</i>	<i>Turbine Unit.1 Floor3</i>
<i>Contractor</i>	<i>One Volts Service Co.,Ltd.</i>	<i>Job Description:</i>	<i>Remove and Re-Installation Insulation Lagging</i>
<i>Customer:</i>	<i>Hongsa Power Co.,Ltd</i>	<i>Start - Ending</i>	<i>1-20 July 2025</i>



Description: Remove and Re-Installation Insulation Lagging

