

# **Report**

***Remove and Re-Installation Insulation Lagging Line Soot to  
GGH Boiler Unit2 Floor5***

***Location***

***Turbine Unit2 Floor5***

***Owner***

***Hongsa Power***

***By***

***One Volts Service Co.,Ltd.***

***Work Duration***

***30-31 July 2025***

|                                                                                                   |                                                                                       |                                                                                      |                                                                                      |
|---------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <b><i>ContractorInspection</i></b><br>.....<br>(.....)<br><b><i>One Volts Service Co.,Ltd</i></b> | <b><i>Approved</i></b><br>.....<br>(.....)<br><b><i>One Volts Service Co.,Ltd</i></b> | <b><i>Commission Inspector</i></b><br>.....<br>(.....)<br><b><i>Hongsa Power</i></b> | <b><i>Commission Inspector</i></b><br>.....<br>(.....)<br><b><i>Hongsa Power</i></b> |
|---------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|

***0163 RP163/25***

## **Scope of Work**

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**

## **Work Procedure**

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**



**One Volts Service Co.,Ltd.**

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)  
Sai Mai Road, Sai Mai Subdistrict  
Bangkok 10220 Tel: 021-28007,081-3235596

|                   |                                                      |                         |                                                      |
|-------------------|------------------------------------------------------|-------------------------|------------------------------------------------------|
| <b>Project :</b>  | <i>Remove and Re-Installation Insulation Lagging</i> | <i>Equipment Item</i>   | <i>Turbine Unit2 Floor5</i>                          |
| <b>Contractor</b> | <i>One Volts Service Co.,Ltd.</i>                    | <b>Job Description:</b> | <i>Remove and Re-Installation Insulation Lagging</i> |
| <b>Customer:</b>  | <i>Hongsa Power Co.,Ltd</i>                          | <b>Start - Ending</b>   | <i>30-31 July 2025</i>                               |



*Description: Remove and Re-Installation Insulation Lagging*

