

Job name: Turbine 1 Extrac electric Floor 2


Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 4 m2

Picture



Before



Before

Remark:

Date: 27/7/2023