

**Job name:** Gland Steam HP Strainer 1 Floor 2

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 2 m2

**Picture**



Before



After

Remark:

Date: 27/7/2023