

Job name: Gland Steam HP Strainer 3 Floor 2

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 2 m2

Picture



Before



After

Remark:

Date: 27/7/2023