

OVS Daily Report

Job name: LP Bypass Pipe Floor 2


Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 32 m2

Picture



Before



Before



Before



Before

Remark:

Date: 27/7/2023

OVS Daily Report

Job name: LP Bypass Pipe Floor 2

Description: Remove and Re-Install Insulation Lagging


Picture



After



After



After



After

Remark:

Date: 27/7/2023