

Job name: Manual Globe Valve 2"

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 1 m2

Picture



Before



After

Remark:

Date: 29/7/2023