

**Job name:** GV 3 (Piping) Floor 3

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 8 m2

**Picture**



Before



After

Remark:

Date: 29/7/2023