

**Job name:** SH panel inlet header R ( Penthouse ) Floor 7


**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 24 m2

**Picture**



Before



After

Remark:

Date: 30/7/2023