

Job name: SH panel outlet header R (Penthouse) Floor 7

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 24 m2

Picture



Before



After

Remark:

Date: 30/7/2023