

**Job name:** SH platen outlet header หัว ( Penthouse ) Floor 7

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 5 m2

**Picture**



Before



After

Remark:

Date: 30/7/2023