

Job name: SH DSHR SPRAY PIPE LINE 4 Floor 7

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 4 m2

Picture



Before



After

Remark:

Date: 30/7/2023