

**Job name:** Cover Boiler Drum Level ( L ) Floor 7

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 2 m2

**Picture**



Before



After



Before



After

**Remark:**

**Date:** 27/7/2023