

Job name: Cover Boiler Drum Level (R) Floor 7

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 2 m2

Picture




Before



After



Before



After

Remark:

Date: 27/7/2023