

Job name: หลังคา BUF # B

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 54 m2

Picture



Before



After

Remark:

Date: 1/8/2023