

Job name: Cold Gas Fan #B

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 69 m2

Picture



Before



After

Remark:

Date: 2/8/2023