

Job name: SH DSHR SPRAY PIPE LINE 1 Floor 7

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 2 m2

Picture



Before



Remove Insulation Lagging



Re-Install Insulation Lagging



Remove Insulation Lagging

Remark:

Date: 4/8/2023