

**Job name:** Water Wall Tube (Sampling) Right Floor 3.5

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 9 m2

**Picture**



Before



After

Remark:

Date: 4/8/2023