



OVS Daily Report

One Volts Service Co.,Ltd.
9/230 Soi Watcharapol 3 Intersection 3
Sub-district Klong Thanon District Sai Mai
Bangkok 10220 Tel:089-488-1651

Job name: Water Wall Tube (Sampling) Front Floor 3.5

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 9 m2

Picture



Before



After

Remark:

Date: 4/8/2023