

Job name: Water Wall Tube (Sampling) Real Floor 3.5

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 9 m2

Picture



Before



After

Remark:

Date: 4/8/2023