

Job name: ผนัง ESP Hopper 136 B

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 5 m2

Picture



Before



After

Remark:

Date: 4/8/2023