



OVS Daily Report

One Volts Service Co.,Ltd.
9/230 Soi Watcharapol 3 Intersection 3
Sub-district Klong Thanon District Sai Mai
Bangkok 10220 Tel:089-488-1651

Job name: Duct lower burner 18 Floor 3

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 8 m2

Picture



Before



After

Remark:

Date: 6/8/2023