


Job name: ESP Hopper 141 A

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 12 m2

Picture



Before



After

Remark:

Date: 6/8/2023