

**Job name:** ESP Hopper 153 B

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 12 m2

**Picture**



Before



After

**Remark:**

**Date:** 6/8/2023