

**Job name:** Coal Pipe Fan mill No.2 Floor 3 ( 5จุด )

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 30 m2

**Picture**



Before



After

**Remark:**

**Date:** 7/8/2023