

Job name: Coal Pipe Fan mill No.4 Floor 3 (5จุด)

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 30 m2

Picture



Before



After

Remark:

Date: 7/8/2023