

**Job name:** ฝา Manhole HP Heater No.1 Floor3

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 3 m2

**Picture**



Before



After

**Remark:**

**Date:** 7/8/2023