


**Job name:** ฝา Manhole HP Heater No.2 Floor3

**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 3 m2

**Picture**



Before



After

Remark:

Date: 7/8/2023