

Job name: ฝา Manhole HP Heater No.3 Floor3


Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 3 m2

Picture



Before



After

Remark:

Date: 7/8/2023