

Job name: Casing Body 2 Floor 3

Description: Remove and Re-Install Insulation Lagging

- ปริมาณ 7.5 m2

Picture



Before



After

Remark:

Date: 8/8/2023