

**Job name:** Crossover Pipe Floor3


**Description:** Remove and Re-Install Insulation Lagging

- ปริมาณ 130 m2

**Picture**



Before



After

Remark:

Date: 8/8/2023