



Daily Report Insulation

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove (SaiMai - Pahol),

Sai Mai Road, Sai Mai Subdistrict Bangkok 10220

Tel : 089-4881651,081-3235596,02-1280077

E-mail : khegwannapa@yahoo.com

Remve and Replacement Insulation Lagging Reheater Desuperheating A,B Boiler Unit3 Floor7

- Remove Lagging
- Remove Insulation
- Installation Lagging
- Replacement Lagging
- Finish

Photos reference



Before



Before



Remove Lagging



Remove Lagging



Daily Report Insulation

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove (SaiMai - Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220

Tel : 089-4881651,081-3235596,02-1280077

E-mail : khegwannapa@yahoo.com

Daily Report Instrument 10/02/25

- Test & Calibration & Install Pressure Gauge 12 EA Turbine Floor 3
- Remove Temperature FGD 16 EA
- Remove & Test & Install Temperature 8 EA Boiler Floor 4

Photos reference



Replacement Lagging



Replacement Lagging



Replacement Lagging



Replacement Lagging



Daily Report Insulation

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove (SaiMai - Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220

Tel : 089-4881651,081-3235596,02-1280077

E-mail : khegwannapa@yahoo.com

Daily Report Instrument 11/02/25

- Test and Calibration level transmittor 8 EA Floor 2
- Remove & Test Temperature 8 EA Boiler Floor 4
- Test and Calibration Pressure Swith 4 EA Floor 2

Photos reference



Replacement Lagging



Replacement Lagging



Finish



Finish