

Report

***Repair and Replacement Insulation Lagging Line Pipe CGF
ESP Unit.3***

Location

ESP Unit.3

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

18 Feb 2025

<i>Contractor Inspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

0070 RP 60/25

Scope of Work

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation New Insulation
5. Install New Lagging

Work Procedure

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation New Insulation
5. Install New Lagging





One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	<i>Repair and Replacement Insulation Lagging</i>	<i>Equipment Item</i>	<i>Boiler Unit.1 floor.2</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Repair and Replacement Insulation Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>18 Feb 2025</i>



Description: Repair and Replacement Insulation Lagging




One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	Repair and Replacement Insulation Lagging	Equipment Item	Boiler Unit.1 floor.2
Contractor	One Volts Service Co.,Ltd.	Job Description:	Repair and Replacement Insulation Lagging
Customer:	Hongsa Power Co.,Ltd	Start - Ending	18 Feb 2025



Description:

Finish